DATE OF INCIDENT	DESCRIPTION OF EVENT	DISTRICT	TOWN/LOCALITY	STREET/ROAD NAME	NUMBER PROPERTIES IMPACTED TOTAL/(internally flooded)	PRIMARY FLOODING CAUSE/S	RISK MANAGEMENT AUTHORITIES	CONCLUSIONS AND RECOMMENDATIONS	EXPECTED TIMESCALES	SITE INVESTIGATION REFERENCE WHERE APPLICABLE
27/07/2019 - 01/08/2019	Over the period from 27-29 July 2019, summer	Burnley	Burnley	Colne Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	storms impacted on Lancashire with high winds and heavy downpours of rain which temporarily		,	Thursby Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Chorley		Church Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
			Adlington	Ollerton Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	overwhelmed local drainage systems			Vicarage Close	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	and caused extensive flooding			Westhoughton Road	2 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	of properties and highways. Then a			York Place	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	further rainfall event on 1 August		Anderton	Roscoe Lowe Brow	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	2019 caused flooding to		Chorley	Kershaw Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	additional			The Bowers	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	properties around Lancashire.		Clayton le Woods	Preston Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Because of the multiple impacts occurring so close together in time, the council has decided to interpret these events as one weather event for the purposes of the investigation.	ole impacts ing so close her in time, council has d to interpret events as aather event purposes of	Euxton	Armetriding Reaches	1 (0)	Surface water flooding from highway due to obstructed culvert	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
				Church Walk	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
				Dawbers Lane	1 (0)	Surface water flooding from highway due to obstructed culvert	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
				Lady Crosse Drive	1 (0)	Riparian responsibilities for watercourse	No Risk Management Authority role	Landowners have been advised of their responsibilities	Not applicable	None required
		Fylde Bryning	Bryning with Warton	Lytham Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
			Lytham St Annes	Links Gate	1 (0)	Surface water run-off from higher land, throttled by confined culvert capacity. Issues of maintenance and condition of the culvert identified from LCC FRM survey	LCC Highways	Investigations continue into culvert problems around the locality	LCC Highways to investigate further. Awaiting update	Detailed site reports will be available from the RMAs as progress is made with these reviews.
				Milner Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required

	Stratford Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Warton Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Westby with Plumpton	Lytham Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Accrington	Exchange Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Rear 43 to 55 Clement Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Oswaldtwistle	George Street	2 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Barrowford	Lucy Street	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Back 211-259 Manchester Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Broadway	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Nelson	Reedyford Road	1 (0)	Surface water flooding from highway, possibly linked to culvert	LCC Flood Risk Management & LCC Highways	Investigations continue into culvert problems around the locality	Communications to be finalised by end of March 2024	Detailed site reports will be available from the RMAs as progress is made with these reviews.
Trawden	Hollin Hall	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and	Not applicable	None required
Fulwood	Watling Street Road	2 (0)	Surface water flooding from highway	LCC Highways	Highway drainage improvement	Not applicable	None required
Preston	Frenchwood Street	1 (0)	Groundwater ingress to private property	LCC Flood Risk Management	Landowners have been advised of their responsibilities	Not applicable	None required
	Park Drive	2 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and	Not applicable	None required
	Claremont Avenue	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Clitheroe	Clitheroe Ribblesdale Avenue		Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Taylor Street	Unknown (unknown)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
Mellor	Mellor Brow	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Helmshore Road	1 (0)	Groundwater ingress to private property	LCC Flood Risk Management	Landowners have been advised of their responsibilities	Not applicable	None required
Haslingden							
Haslingden Rawtenstall	Burnley Road East	1 (0)	Groundwater ingress to private property	LCC Flood Risk Management LCC Highways	Landowners have been advised of their responsibilities All drainage systems inspected and	Not applicable Not applicable	None required
	Accrington Oswaldtwistle Barrowford Nelson Trawden Fulwood Preston	Westby with Plumpton Lytham Road Accrington Exchange Street Rear 43 to 55 Clement Street Oswaldtwistle George Street Barrowford Lucy Street Back 211-259 Manchester Road Broadway Nelson Reedyford Road Trawden Hollin Hall Fulwood Watting Street Road Preston Park Drive Claremont Avenue Ribblesdale Avenue Taylor Street	Warton Street	Westby with Plumpton Lytham Road 1 (0) Surface water flooding from highway Exchange Street 1 (0) Surface water flooding from highway Rear 43 to 55 Clement Street 1 (0) Surface water flooding from highway Rear 43 to 55 Clement Street 1 (0) Surface water flooding from highway Street Oswaldtwistle George Street 2 (0) Surface water flooding from highway Barrowford Lucy Street 1 (0) Surface water flooding from highway Back 211-259 Manchester Road 1 (0) Surface water flooding from highway Broadway 1 (0) Surface water flooding from highway Surface water flooding from highway Freston Reedyford Road 1 (0) Surface water flooding from highway Surface water flooding from highway possibly linked to culvert Trawden Hollin Hall 1 (0) Surface water flooding from highway Fulwood Watting Street Road 2 (0) Surface water flooding from highway Frenchwood Street 1 (0) Groundwater ingress to private property Park Drive 2 (0) Surface water flooding from highway Claremont Avenue 1 (0) Surface water flooding from highway Claremont Avenue 1 (0) Surface water flooding from highway Claremont Avenue 1 (0) Surface water flooding from highway Surface water flooding from highway Claremont Avenue 1 (0) Surface water flooding from highway	Strafford Road	Stratford Road 1 (0) Surface water flooding from highway LCC Highways All drainage systems inspected and cleaned	Stratord Road

					LCC Highways		Not applicable	None required
		Coppice Drive	1 (1)	Surface water flooding from highway	, and g	Highway drainage improvement works completed 2019.		
		Lobden Crescent	1 (1)	Surface water flooding from highway	LCC Highways	Highway drainage improvement works completed 2019.	Not applicable	None required
		Market Street	4 (3)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Northgate	1 (0)	Surface water runoff from higher land was funnelled through the estate via roads and ginnels.	LCC Highways	Extensive rootcutting and relining of the carrier drain on Wallbank Drive, with selective kerb/gully improvements elsewhere around the estate, were carried out later in 2019.	Not applicable	None required
	Whitworth	Sandbank Gardens	2 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Southgate	10 (4)	Surface water runoff from higher land was funnelled through the estate via roads and ginnels.	LCC Highways	Extensive rootcutting and relining of the carrier drain on Wallbank Drive, with selective kerb/gully improvements elsewhere around the estate, were carried out later in 2019.	Not applicable	None required
		Spinners Drive	1 (0)	Surface water flooding from neighbouring land - individual / private drainage issue	LCC Flood Risk Management	Landowners have been advised of their responsibilities	Not applicable	None required
		Tong End	1 (1)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Wallbank Drive	8 (7)	Surface water runoff from higher land was funnelled through the estate via roads and ginnels.	LCC Highways	Extensive rootcutting and relining of the carrier drain on Wallbank Drive, with selective kerb/gully improvements elsewhere around the estate, were carried out later in 2019.	Not applicable	None required
South Ribble	Bamber Bridge	Station Road	1 (1)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Leyland	Balcarres Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Penwortham	Pope Lane	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
West Lancashire	Bispham	Bispham Jacksons Lane		Culverted watercourse under highway overflowed and flooded highway as well as adjoining land	LCC Highways	The trashscreen was cleared at the time of the event	Not applicable	None required
		Gorst Lane	1 (0)	Surface water flooding from highway, found to be casued by tree roots in outlet systems	LCC Highways	Highway drainage improvement works completed 2019.	Not applicable	None required
		Liverpool Road South	1 (0)	Surface water flooding from neighbouring	No Risk Management	Landowners have been advised of their	Not applicable	None required
		'		land - individual / private drainage issue	Authority role	responsibilities		
	Burscough	Mill Lane	1 (0)	land - individual / private drainage issue Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Burscough	·	1 (0)		LCC Highways	All drainage systems inspected and	Not applicable	None required
	Burscough	Mill Lane		Surface water flooding from highway	LCC Highways LCC Highways West Lancashire district council, UU, LCC	All drainage systems inspected and cleaned All drainage systems inspected and	• • • • • • • • • • • • • • • • • • • •	·
	Burscough Hesketh Bank	Mill Lane Moss Nook	1 (0)	Surface water flooding from highway Surface water flooding from highway	LCC Highways LCC Highways West Lancashire district council, UU, LCC Highways & LCC Flood	All drainage systems inspected and cleaned All drainage systems inspected and cleaned Private works have corrected problems	Not applicable	None required
		Mill Lane Moss Nook Red Cat Lane	1 (0)	Surface water flooding from highway Surface water flooding from highway Very localised flooding from private drainage	LCC Highways LCC Highways West Lancashire district council, UU, LCC Highways & LCC Flood Risk Management	All drainage systems inspected and cleaned All drainage systems inspected and cleaned Private works have corrected problems with septic tank/s All drainage systems inspected and	Not applicable Not applicable	None required None required
	Hesketh Bank	Mill Lane Moss Nook Red Cat Lane Moss Lane	1 (0) 8 (0) 1 (1)	Surface water flooding from highway Surface water flooding from highway Very localised flooding from private drainage Surface water flooding from highway	LCC Highways LCC Highways West Lancashire district council, UU, LCC Highways & LCC Flood Risk Management LCC Highways	All drainage systems inspected and cleaned All drainage systems inspected and cleaned Private works have corrected problems with septic tank/s All drainage systems inspected and cleaned All drainage systems inspected and	Not applicable Not applicable Not applicable	None required None required None required

		Scarisbrick	Southport Road	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Skelmersdale	Birleywood	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
			lvydale	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
			Lime Grove	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
			Tarlswood	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Wrightington	Church Lane	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
	Wyre	Cabus	Croston Barn Lane	2 (1)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Fleetwood	Fleetwood Road	1 (0)	Surface water flooding from highway, exacerbated by passing traffic creating bow waves	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Forton	Wallace Lane	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required
		Thornton	Kingsley Close	1 (0)	Surface water flooding from highway	LCC Highways	All drainage systems inspected and cleaned	Not applicable	None required